## FEDERAL COMMUNICATIONS COMMISSION 445 12<sup>th</sup> STREET SW WASHINGTON DC 20554

MEDIA BUREAU AUDIO DIVISION

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/

Anne Goodwin Crump, Esq. Fletcher, Heald & Hildreth 1300 North 17<sup>th</sup> Street, 11<sup>th</sup> Floor Arlington, Virginia 22209 PROCESSING ENGINEER: Edward Lubetzky

TELEPHONE: (202) 418-2700 FACSIMILE: (202) 418-1410/11 MAIL STOP: 1800B2-EAL

INTERNET ADDRESS: Edward.Lubetzky@fcc.gov

APR 1 7 2012

Re: M&M Broadcasters, Ltd.

KLRK(AM), Mexia, TX

Facility Identification Number:

Construction Permit: BP-20100514ABJ License Application: BMML-20120312ADH

Dear Ms. Crump:

This is in reference to the above-captioned license application. The staff's review shows the following deficiencies with application:

- 1. The manufacturer and type of antenna monitor is not specified in item 8 of the FCC Form 302-AM (Page 4) of the application.
- 2. The make, model number and description of the sample lines were not provided.
- 3. The make and model of the fourth sampling device was not specified.
- 4. The manufacturers rated accuracy of the sampling devices was not provided.
- 5. An exhibit showing a comparison between the geometry of the array as built and as authorized was not provided.
- 6. The reference datum (NAD 83 or NAD 27) was not provided for the location of the field strength measurements in the directions of the directional pattern minima and maxima.

Further action on the subject license application will be withheld until the applicant submits an amendment addressing the deficiencies described above. Failure to respond within 30 days from the date of this letter may result in the dismissal of the application pursuant to 47 CFR Section 73.3568(a) (1).

Sincerely,

Ann Gallagher Audio Division

Media Bureau

cc: Charles W. Staples M&M Broadcasters, Ltd.